









ALL DIMENSIONS IN MM.



KP 04.1 / 1.6

KP 04.2 / 2.0



P = PLAIN PIN

T = THREADED PIN

BP = BEND PLAIN PIN

BT = BEND THREADED PIN

**APPLICATION DRAWING FOR MODEL
NO. KP 04.1 / 1.6 & KP 04.2 / 2.00 -
P/T/BP/BT (ZINC HINGE) **PC - 01****